

**TOUR NOTE OF ABHISHEK SINGH, IAS, DM & COLLECTOR, DHALAI DISTRICT FOR  
VISIT TO KACHIMCHERRA AND WEST NALICHERRA VILLAGE COMMITTEE  
UNDER AMBASSA RD BLOCK.**


**27.09.2012:**

I along with SE, PWD (R&B), Dhalai, EE, PWD (R&B), Ambassa, BDO, Ambassa and the representative of PRI visited the Kachimcherra and West Nalicherra VC on 27<sup>th</sup> September, 2012. During the visit following issues were brought out which require immediate action by the concerned officials:

1. The road from KA road to Kachimcherra was formed 5-6 years ago but the total stretch has not yet been brick soled. The people of the area demanded for the black topping of the road. However, since the road belongs to TTAADC, the ZDO, Dhalai and EE, PWD (ADC), Shikaribari may look into the matter and take up the work as per the action plan and availability of the fund. Meanwhile, the BDO, Ambassa is requested to take up the brick soling work under MGNREGA material component from the district/block share.
2. There is a demand for providing an irrigation scheme through sluice gate/diversion scheme by the Water Resource department for 120 to 130 acres of agricultural land which is not provided with any irrigation facility. The EE, WR, Kamalpur shall visit the Kachimcherra VC within a week with intimation to the local PRI to take up the feasibility analysis of the project and submit a report by 15<sup>th</sup> October, 2012.
3. It was also reported that many of the habitations of Kachimcherra are only partly covered with the power connectivity. The DGM, TSECL, Ambassa is requested to make a Special project to cover the all-partly covered habitations which would not be taken up under RGGVY Phase-II programme. AGM, TSECL, Dhalai is also requested to do similar exercise to all other partly covered habitations in Dhalai district which would not be covered under RGGY Phase-II for making special project and submit by 15<sup>th</sup> October, 2012.
4. A demand for a deep tube well in the Kachimcherra VC near the TSR camp was also placed. The EE, DWS is requested to see the feasibility as well as covering these habitations as per his annual action plan immediately. A report in this respect may be submitted into the undersigned within the first week of October, 2012.
5. BDO, Ambassa shall enquire into the non-coverage of AWCs for sanitation facilities in Raj Kumar Chaudhury Para and Mahendra Debbarma Para of Kachimcherra VC and take up the work, if it was sanctioned by the DWSC in 2009-10 for taking up by the Block. M/S DWSC, Dhalai is requested to ascertain the implementing agency for construction of toilets AWCs for the above locations and confirm within 30<sup>th</sup> September, 2012.
6. A box culvert on the way of TSR camp in Kachimcherra was found to be damaged and even after the visit of undersigned last year wherein necessary instruction was

given to EE, RD, Ambassa and BDO, Ambassa no action has been taken by EE, RD, Ambassa and BDO, Ambassa for taking up new construction. In the last tour note of undersigned EE, Ambassa was directed to dismantle the parts of the broken bridge and place it on the other side to prevent further river bank erosion. An estimate shall be prepared by BDO, Ambassa for taking up box culvert at the said location and the fund may be placed to EE, RD, Ambassa from district share to take up the work immediately.

7. On the way from Kachimcherra to Ghantacherra one of the part of PMGSY road constructed by HSCL was found to be badly damaged due to side erosion by nearby cherra. SE, PWD, Dhalai is requested to take up the matter with HSCL for providing protection wall and taking up necessary repair and maintenance immediately.
8. It was reported that Nalicherra High School is functioning without the Head Master and sufficient numbers of teachers since February, 2012. The DEO, Dhalai is requested to look into the matter and take necessary action for proper functioning of this high school. A report this regard may be submitted to the undersigned within first week of October, 2012.
9. The condition of PMGSY road under HSCL from KA road to Ghantacherra was found to be badly damaged. The representative of HSCL and the agency engaged were asked by SE, PWD, Dhalai to take up the necessary works immediately so as to make the road motorable before Durgapuja. The SE, PWD, Dhalai is requested to monitor and supervise the work performed by HSCL on this stretch weekly.

  
(ABHISHEK SINGH, IAS)  
District Magistrate & Collector  
Dhalai district, Jawaharnagar.

-----  
**GOVERNMENT OF TRIPURA  
OFFICE OF THE DISTRICT MAGISTRATE & COLLECTOR  
DHALAI DISTRICT: AMBASSA.**

No.F.10 (3)/DM (D)/CON/10/3228-37.

28.09.2012

**To**

- The SE, PWD (R&B), Dhalai, Jawaharnagar.
- The BDO, Ambassa RD Block.
- The EE, PWD (R&B), Ambassa
- The EE, PWD (WR), Kamalpur
- The EE, RD, Ambassa Division, Jawaharnagar.
- The M/S DWSC, Dhalai, Jawaharnagar.
- The DEO, Dhalai, Jawaharnagar.
- The Dy. Director, Agriculture, Dhalai, Jawaharnagar.

**Copy to:**

- ❖ The Principal Secretary, PWD Department, Government of Tripura for kind information.
- ❖ The Secretary, Rural Development Department, Government of Tripura for kind information.

  
District Magistrate & Collector  
Dhalai district, Jawaharnagar.